UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,110,263 B2

Page 1 of 1

APPLICATION NO.: 10/797753

DATED

: September 19, 2006

INVENTOR(S)

: He et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Figures 2A & 2B

[Ref no.] 200 should be deleted.

Figure 5

[Ref no.] 560 should be deleted.

Figure 7

[Ref no.] 724 should be deleted.

Column 3

Line 8, "...dielectric 270..." should read --...dielectric layer 270...--.

Line 43, "...traces 314..." should read --...signal traces 324 344...-.

Column 4

Line 4, "...the slot width..." should read --...the slot width 434...-.

Line 10-11, "...the inner layers..." should read --...the inner layers 570...--.

Column 5

Lines 43-46, "8. ...located alone..." should read --8. ...located along...-.

Column 6

Lines 37, "...the a assembly..." should read --...the assembly...--.

Signed and Sealed this

Fifteenth Day of July, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office